

Ball Turning with Manual Numerical Control, version 2.1.0

By **R. G. Sparber**

Copyright protects this document.¹



I suspect that just about everyone is familiar with Computer Numerical Control (CNC). It has changed the look of most products we own. Before CNC, products were rather boxy with lots of straight lines and planes. CNC frees designers from this simplicity and lets us have complex, curved surfaces in our toasters, cars, and everything in between.

Many hobbyists have taken the plunge and run CNC in their shop. Others, like me, have resisted the pull because we enjoy doing things manually. Yet, there is a middle ground: Manual Numerical Control (MNC). This method of machining can create amazing shapes but the work can also be mind numbing and demanding at the same time.

¹ You are free to copy and distribute this document but not change it.

One way to combat the demands of MNC, is to have a program supervise your machining. It can tell you what to do next and also hold your place if you want to take a break. This article presents such a program that runs on a TI-83 Plus calculator and lets you turn a ball, crown, or full radius using only a parting tool for a cutter.

The surfaces created with this procedure can be made to look very nice. But do not expect the process to turn out anything precision. You would lose your mind trying to take that many cuts.

I expect there are two kinds of people that will be interested in this program. The first group would like to understand how CNC works. Using the program will give them firsthand knowledge of how a series of cutting coordinates creates a surface. The second group has no interest in CNC but wants to cut balls, crowns, or full radii on their lathe without any special tooling. Hopefully this program will satisfy both groups.

If you own a TI-83 Plus or compatible programmable calculator and wish a copy of the program file, please contact me directly at rgsparber@aol.com. I will send you the file to download directly into your calculator.

One bit of jargon: DOC means Depth Of Cut.

Background

Over the last few decades, I have played around with MNC a few times. My first exposure to this concept was in Guy Lautard's first Bedside Reader, page 72. It inspired me to write a program that ran on an HP pocket calculator. This calculator has a very limited alpha numeric screen making it easy to get confused.


The next program ran in Excel. Generate and print out the spreadsheet and bring into the shop. This was a big improvement and essentially free. Since it is just a piece of paper, I could easily move forward and backward through the data if I got confused. Yet, it was still possible to lose my place which typically then caused a defect in the surface that could not be removed.

Recently I have started to play with a TI-83 Plus calculator which has an excellent alphanumeric screen and plenty of memory. So, just for fun, I decided to take a crack at this old chestnut again.

The program feeds me data similar to the spreadsheet but with a few important improvements. I define the size of the ball, crown, or full radius and shank in my shop and don't need to run to my PC and print something out. It also keeps track of where I am at all times. And lastly, I can move forward and back in the data if I get confused. Just like with the spreadsheet, I can walk away at any time and the data is saved.

When using the spreadsheet, I tended to make one error on every surface. So far, I have made no mistakes using the calculator.

Overview



This software tool will let you turn a ball that is attached to a shank. The user specifies the workpiece's initial diameter, finished ball diameter, finished shank diameter and the program guides you in the machining operations.

This is done in three passes: outline turning, a roughing pass, and a finish pass.

The outline turning reduces the workpiece's diameter to equal the roughing diameter of the ball and the roughing diameter of the shank.

The roughing pass cuts steps almost as wide as your parting tool and about .01" away from the finished surface². The work goes fast.

The finish pass consists of many light cuts that land close to or on the finished surface. As Guy Lautard explains, a file is used to get to the final shape. The result is a nice looking ball.


² This value is user specified.

Shop Experience

All steps are explained on the TI-83 Plus's screen.




The outline of the ball and shank are roughed out.




Using a parting tool, the roughing pass is performed. The step size is set to be of equal width and just a little narrower than the parting tool's width. This minimizes the time it takes to rough out the ball and associated shank. Here you see four plunge cuts with the parting tool to roughly define the ball.

If you have a form tool or ball turning attachment, this may be as far as you need to go.




Here is a typical screen during the shaping of the ball. If you presses ENTER, the next longitudinal (Z axis) and cross feed (X axis) values appear. If you press "-", the previous set of numbers are displayed. You can also take a break by pressing "5". After a few minutes, the calculator powers down. Just press the ON button and then the ENTER button and you will be back to the same place in the program.



This finish pass was done with a 0.025" wide step size. There is a tradeoff between the coarseness of the steps and the ability of the user to retain sanity.

It is very tedious when you are taking a large number of cuts. Fortunately, the program lets you stop at any time, pick up at that point later, move forward, and backward, in the position of the cutter. The experience certainly gives you an appreciation for how CNC works.



Using the method describe by Guy Lautard, I coated the surface with dye.




A file was then used to remove the steps. As you get close to the final shape, the dye will show as fine lines. When the lines are gone, it is time to switch to emery cloth for the final finishing.



Since I can cut a ball, I can cut the end of a piece of round stock so it has a crown. In this case the stock is 1" in diameter and the crown has a 4" diameter.

Unlike a ball cutting attachment, the program can handle a ball or segment of a ball of any diameter. So if you wanted a crown with a diameter of 40", it is just a matter of entering the number.

Theory




This is a top view of the workpiece showing only from the center of rotation to the radius. The shank begins at a distance "g" from the origin.



Notice that I have slipped in a bit of flexibility here in the form of distance "f". If turning a ball, the distance from the center of the ball to the center of rotation is zero. But if "f" is not zero, I am turning a disk with the given radius at its edges. A "full radius" has this shape which was cut with the program in control.


This program is rather large in order to make it as easy as possible for the user. Buried deep in the code within subroutine BTU12 is a single equation. That is all it takes to define a ball, crown, or full radius. This equation translates a longitudinal value to a crossfeed value.

The rest of this theory will only discuss forming a ball.




The first step in making the ball is to cut the outline, shown in green. This is done by first facing the right end using a left hand cutter. Then the roughing radius is turned. And finally, the roughing radius of the shank is turned using both a left and right hand cutter or a parting tool depending on how much room you have.

The right end of the workpiece is my $Z=0$ reference plane. The outside diameter is my $X=0$ surface.



Next, a series of roughing cuts are made using a parting tool to form a stair step that follows the roughing surface.



The front left corner of the tool cuts the surface of the ball from the equator to right end the of the ball. By moving in this direction, the operator is always feeding in so avoids cross feed backlash.

After the right half of the ball is formed, the front right corner of the parting tool is used to cut from the equator to the start of the shank. This, again, avoids crossfeed backlash.

All of this cutter movement is handled by the program and the user is simply given longitudinal and crossfeed settings.

The finish pass follows the same logic as the roughing pass. The only difference is how much you longitudinally advance the parting tool for each cut. This distance is mostly determined by how much of this repetitive cutting you can stand before going nuts. One instant of distraction and the cutter can go too far. The error will then stick out like a sore thumb.

Frequent breaks are a good idea. Just walk away from the lathe and calculator. The calculator will automatically power down after a few minutes. Press the ON button and then ENTER to return to where you were before your break.

Thanks to Corey for telling me the proper term for "full radius".

I welcome your comments and questions.

Rick Sparber
Rgsparber@aol.com
Rick.Sparber.org

Appendix: The Program


Subroutine Listing

BTR - Ball Turning Tool	15
BTR1 initialization of variables.....	16
BTS - Setup.....	17
BTS1 - prompt for parting tool width and store in C	18
BTS2 - prompt for finish DOC and store in D	18
BTS3 - prompt for finish step size and store in E.....	18
BTS4 - prompt for crossfeed dial size and store in L	19
BTS5 - sign of L flags crossfeed dial as radius or diameter	20
BTS6 - select the profile	21
BTS8 - DRO or DIAL with V as flag.....	23
BTS7 - CROSSFEED parameters.....	24
BTU - Main.....	25
WP1 - prompt with titles.....	26
BTU0 - prompt and pause utility	28
BTU1 - finished ball diameter prompt.....	29
BTU2 - finished shank diameter prompt	30
BTU3 - calculate outline cuts	31
BTU4 - tell operator to face end and turn ball rough outline plus turn shank to roughing diameter	32

BTU5 - zero parting tool.....	34
BTU6- make equator to origin roughing cuts if this is a ball or crown roughing cuts	35
BTU61 - translates from internal radius distance to crossfeed dial setting and display to user	37
BTU7 make equator to shank interface roughing cuts.....	40
BTU71 back up on step if possible	42
BTU8 make equator to origin finish cuts.....	43
BTU9 make equator to shank finish cuts	45
BTU10 using a left hand cutter, cut finish pass on shank.....	47
BTU11 tell user to back parting tool away from max OD.....	48
BTU12 - translate any Z in inches less than the diameter of the ball and return X in thou; uses vector [A] to set size and location from origin.....	49

Variables Used

- A - finished ball diameter in inches
- B - finished shank diameter in inches
- C - parting tool width in thou
- D - finish Depth Of Cut (DOC) in thou
- E - finish step size in thou
- F - roughing ball diameter in inches
- G - roughing shank diameter in inches
- H - OAL of cylinder containing ball in inches
- I - number of Z steps (used to right and then left of equator and for rough and finish cuts)
- J - width of each cut step (used to right and then left of equator and for rough and finish cuts) in inches
- K - cut counter steps (used to right and then left of equator and for rough and finish cuts)
- L - size of crossfeed dial; if >0 , then it is a radius dial; if <0 it is a diameter dial in thou
- M - current X axis internal radius dial position: integer part is full turns, fractional part is thou
- N - distance from origin to shank in inches
- O - number of full crossfeed dial revolutions for the given X value
- P - dial value (may be for a radius or diameter dial)
- Q - temp
- R - profile control (0 = ball, 1 = crown, 2 = full radius)
- S - used only by BTU6 and BTU8
- T
- U
- V - if crossfeed uses just a dial, V not equal to 1; if crossfeed has a DRO, $V = 1$
- W - temp
- X - current X axis value in thou
- Z - current Z axis value in inches



[A] - a 1 x 9 matrix used to pass the surface defining equation its parameters

1. a - not used at the present time
2. b - not used at the present time
3. c
4. d
5. e
6. f - not used at the present time
7. g- not used at the present time
8. h - temp
9. i - temp

BTR - Ball Turning Tool

```
{1,9} → dim([A])      define shape vector and zero all elements
LBL D
MENU ("BALL TURN V1.2", "RUN", A, "SET UP", B, "INITILIZE", E,
"EXIT",C)
LBL A
Prgm BTU
GO TO D
LBL B
Prgm BTS
GO TO D
LBL E
PrgmBTR1
GO TO D
LBL C
ClrHome
PrgmA      program A is main calling menu
END
```

BTR1 initialization of variables

-1 -> V	dial (if V=1 it would be DRO)
187.5 → C	parting tool width
10 → D	finish DOC
50 → E	finish step size
100 → L	dial has 100 thou/rev and since >0, is radius
0→R	profile set to ball
RETURN	
END	

BTS - Setup

Store parting tool width, roughing - finish cut distance, finish pass step size, crossfeed dial size, radius vs diameter crossfeed dial

LBL A

MENU("SET UP", "PARTING TOOL", B, "FINISH DOC", C, "FINISH STEP", D, "CROSSFEED", G, "PROFILE", H, "EXIT", E)

LBL B

Prgm BTS1 C stores parting tool width
GO TO A

LBL C

Prgm BTS2 D stores finish DOC
GO TO A

LBL D

Prgm BTS3 E stores finish step size
GO TO A

LBL G

Prgm BTS7 DRO/DIAL, radius/diameter, dial size
GO TO A

LBL H

Prgm BTS6 select profile R - (0 = ball, 1 = crown, 2 = full radius, 3 =
 concave)

GO TO A

LBL E

RETURN
END

BTS1 - prompt for parting tool width and store in C

```
"PARTING TOOL ", "→Str1  
2→T  
C→W  
PrgmWP1  
W→C  
RETURN  
END
```

BTS2 - prompt for finish DOC and store in D

```
"FINISH DOC" ->Str1  
2->T  
D->W  
PrgmWP1  
W->D  
RETURN  
END
```

BTS3 - prompt for finish step size and store in E

```
"FINISH STEP SIZE"->Str1  
2->T  
E->W  
PrgmWP1  
W->E  
RETURN  
END
```

BTS4 - prompt for crossfeed dial size and store in L

LBL C

"DIAL SIZE "-> Str1

2->T tell WP1 units are THOU

IF L>0 if L positive, this is a radius dial so use as is

THEN

L->W

ELSE otherwise, this is a diameter dial so double and invert
sign before showing user

-L*2->W

END

PrgmWP1 display value and prompt for change

Abs(W) → W force L to be positive so it does not interfere with
radius/dia. flag

IF L>0 if L positive, this is a radius dial so use as is

THEN

W -> L

ELSE otherwise, this is a diameter dial so cut in half and make
negative before storing internally

-W/2 -> L

END

RETURN

END

BTS5 - sign of L flags crossfeed dial as radius or diameter

```
LBL C
  IF L>0
  THEN
    MENU("SETS RADIUS ", "KEEP", A, "MAKE DIAMETER",B)
  ELSE
    MENU("SETS DIAMETER ", "KEEP",A, "MAKE RADIUS",B)
LBLB
  -L →L
  GO TO C
LBL A
  RETURN
  END
```

BTS6 - select the profile

R - profile control (0 = ball, 1= crown, 2 = full radius)

LBL D

ClrHome

OUTPUT(1,1,"SELECTED PROFILE ")

IF R = 0

THEN

OUTPUT(2,1," IS BALL.")

GO TO E

END

IF R = 1

THEN

OUTPUT(2,1," IS CROWN.")

GO TO E

END

IF R = 2

THEN

OUTPUT (2,1," IS FULL RADIUS.")

GO TO E

END

OUTPUT(2,1," IS UNKNOWN.")

otherwise, unknown

LBL E

PrgmBTU0

prompt to press ENTER and pause

```
    ClrHome
    MENU("PROFILES","BALL", A, "CROWN", B, "FULL RADIUS",C,
"EXIT", F)
LBL A
    0→R
    GO TO D

LBL B
    1→R
    GO TO D

LBL C
    2→R
    GO TO D

LBL F
    RETURN
    END
```

BTS8 - DRO or DIAL with V as flag

LBL A

```
IF V=1          if V=1 it means DRO
THEN
Menu("HAVE DRO","KEEP",B,"MAKE IT DIAL",C)
ELSE
Menu("HAVE DIAL", "KEEP",B, "MAKE IT DRO",D)
END
```

LBL B
RETURN

```
LBL C
-1 -> V        any V not equal to 1 means DIAL
GO TO A        review change
```

```
LBL D
1 -> V         set V to 1 to flag DRO
GO TO A        review change
END
```

BTS7 - CROSSFEED parameters

PrgmBTS8	set flag for DRO versus DIAL
PrgmBTS5	set flag for radius versus diameter
IF V =1	if using a DRO, return
THEN	
RETURN	
END	
PrgmBTS4	if not DRO, prompt for dial size
RETURN	
END	

BTU - Main

Prompt for finished ball diameter or radius, finished shank diameter, and initial workpiece OD

Calculate outline dimensions.

Tell operator to face end of bar and turn to roughing cut diameters using left and right hand cutters.

Tell operator to install parting tool with width specified in setup. Set origin. Guide operator over roughing pass.

Guide operator over finish pass.

Design interface so operator can stop at any time and restart later without confusion.

Prgm BTU1	get finished ball diameter
Prgm BTU2	get finished shank diameter
Prgm BTU3	calculate outline cuts
Prgm BTU4	tell operator to face end and turn ball rough diameter plus shank rough diameter
PrgmBTU5	tell operator to verify parting tool width and then zero parting Tool
PrgmBTU6	make equator to origin roughing cuts
PrgmBTU7	make equator to ball/shank interface roughing cuts
PrgmBTU8	make equator to origin finish cuts
PrgmBTU9	make equator to shank finish cuts
PrgmBTU10	using a left hand cutter, cut finish pass on shank
RETURN	
END	

WP1 - prompt with titles

```
IF T=1                T indicates inches, thou, or blank after value
THEN
"INCHES."→Str2
END

IF T=2
THEN
"THOU."→Str2
END

IF T=3
THEN
""→Str2
END

LBL C
ClrHome
1 + iPart((16-length(Str1))/2)→Q    center title held in string 1
OUTPUT(1,Q,Str1)
DISP ""
DISP "PRESENT VALUE IS"
OUTPUT(3,1,W)                        value is passed to subroutine in W
OUTPUT(3,7,Str2)
DISP ""                               blank DISP commands move line pointer
                                       Along because OUTPUT does not do it

DISP ""
DISP "1)KEEP 2)CHANGE"
WHILE 1
GETKEY → Q                            scan for 1 or 2 being pressed. Ignore all else
WHILE Q=0
GETKEY→Q
END

IF Q=92
THEN
RETURN
END
```

```
IF Q=93  
THEN  
GO TO B  
END
```

```
END  
LBL B  
DISP ""  
DISP "NEW VALUE="  
INPUT W  
GO TO C      after getting new value, restart dialog  
END
```

BTU0 - prompt and pause utility

```
OUTPUT(8,1,"PUSH ENTER")  
PAUSE  
RETURN  
END
```

BTU1 - finished ball diameter prompt

```
ClrHome
IF R=0
THEN
DISP " BALL PROFILE"
END

IF R=1
THEN
DISP " CROWN PROFILE"
END

IF R=2          if cutting full radius, change prompt text
THEN
DISP " FULL RADIUS"
DISP "  PROFILE"
OUTPUT(4,1," RADIUS")
OUTPUT(5,1,"IN INCHES")
DISP ""
DISP ""
DISP ""
DISP ""          four DISP "" put INPUT on line 5
INPUT A
2*A→A          convert to diameter in inches
RETURN
ELSE
OUTPUT (3,1,"FINISHED BALL")
OUTPUT (4,1," DIAMETER ")
OUTPUT(5,1,"IN INCHES ")
DISP ""
DISP ""
DISP ""
DISP ""
DISP ""
INPUT A
RETURN
END
```

BTU2 - finished shank diameter prompt

ClrHome

OUTPUT (1,1,"FINISHED SHANK")

OUTPUT (2,1," DIAMETER ")

OUTPUT(3,1,"IN INCHES ")

DISP ""

DISP ""

DISP ""

DISP ""

INPUT B

RETURN

END

BTU3 - calculate outline cuts

A + (.002*D) → F

ball roughing/outline diameter in
inches

B + (.002*D) → G

shank roughing/outline
Diameter in inches

IF R=1

this is a crown cut

THEN

GO TO A

END

IF R=2

this is a full radius

THEN

GO TO B

END

$(F/2) + \text{SQRT}((F/2)^2 - (G/2)^2) \rightarrow H$

OAL of cylinder containing ball in
inches

RETURN

LBL A

$(F/2) - \text{SQRT}((F/2)^2 - (G/2)^2) \rightarrow H$

OAL of cylinder containing crown in
inches

RETURN

LBL B

F → H

OAL of cylinder is roughing diameter of ball

RETURN

END

BTU4 - tell operator to face end and turn ball rough outline plus turn shank to roughing diameter

```
ClrHome
OUTPUT(1,1,"FACE END")
OUTPUT(2,1, "OF WORKPIECE.")
PrgmBTU0
```

```
IF R=1                we are cutting a crown so skip outline of ball
THEN
GO TO A
END                  for ball and full radius, use ball equations
```

```
ClrHome
OUTPUT(1,1,"TURN DIAMETER")
OUTPUT(2,1, "OF")
```

```
IF R=2                if cutting a full radius
THEN                  then use alternate text
OUTPUT(2, 4"DISK ")
2*D → W
ROUND(W,0)→W
OUTPUT(3,1,"PLUS")
OUTPUT(3,6, W)
OUTPUT(3,9,"THOU.")
GO TO B
END
```

```
ROUND(F,3) → W
OUTPUT(2,4, W)
OUTPUT(3,1, "INCHES")
LBL B
OUTPUT(4,1,"FOR OAL OF")
ROUND(H,3)→W
OUTPUT(4,12,W)
OUTPUT(5,1,"INCHES")
PrgmBTU0
LBL A
```

```
IF B = 0          if the shank finish diameter is zero, skip outline of it
THEN
RETURN
END
```

```
ClrHome
OUTPUT(1,1,"TURN DIAMETER")
OUTPUT(2,1, "OF")
OUTPUT(2,4, G)
OUTJPUT(2,11, "INCHES")
OUTPUT(3,1,"FOR LENGTH OF")
OUTPUT(4,1,"SHANK.")
PrgmBTU0
RETURN
END
```

BTU5 - zero parting tool

ClrHome

OUTPUT(1,1," LEFT SIDE OF")

no backlash problem with Z because
of DRO

OUTPUT(1,14,C)

OUTPUT(2,1,"THOU PARTING "

OUTPUT(3,1," TOOL ON RIGHT ")

OUTPUT(4,1," END OF WORKPIECE ")

OUTPUT(5,1," AND ZERO Z AXIS ")

PrgmBTU0 prompt and pause

ClrHome

OUTPUT(1,1,"PLACE FRONT OF")

OUTPUT(2,1," PARTING TOOL")

OUTPUT(3,1," ON OD OF")

OUTPUT(4,1,"WORKPIECE AND")

OUTPUT(5,1,"ZERO X AXIS")

PrgmBTU0 prompt and pause

RETURN

END

BTU6- make equator to origin roughing cuts if this is a ball or crown roughing cuts

```
F/2 → [A](1,3)           initialize form vector for roughing cut
F/2 → [A](1,4)
F/2 → [A](1,5)

PrgmBTU11                 tell user to back cutter away from max OD

IF R=1                    if this is a crown cut, Z distance is H
THEN
H → S
ELSE
F/2 → S                   if this is a ball or full radius cut, distance is roughing
                           radius of ball
END

iPart(S/(C*0.001)) + 1 → I   calc # of Z steps to go from equator to right
                             end of ball or for crown on the roughing cut
                             by rounding up
S / I → J                 calc width of each Z step in inches
0 → K                     start of loop similar to FOR(K,0,I) except I can modify K
LBL B

IF K>I
THEN
RETURN
END

LBL A

S - (K*J) → Z             in inches
PrgmBTU12                 take Z and generate X in thou
PrgmBTU61                 output next (X,Z) pair saying to move Z first and
                           then X; take into consideration radius/diameter dial
PrgmBTU71                 go to next step or go back one if possible (W flag)

IF W>0                    flag = 1 means return to the top of the loop with
                           decremented or unchanged count value
```

THEN
GO TO A
END

give last location again

K+1 → K
GO TO B
END

for normal loop cycle, increment K
end of loop rough cutting from equator to right end


```

LBL B
IF L < or = 0      if this is a diameter dial,
THEN
2*P -> P          then double dial position
END

ROUND(Z,3) → W    reusing W for rounded Z (xx.xxx)
ClrHome
OUTPUT(1,1,"MOVE OVER TO")
OUTPUT(2,1," Z= ")
OUTPUT(2,4,W)
OUTPUT(2,10,"INCHES")
OUTPUT(3,1,"AND THEN IN")

IF V=1            if we have a DRO, just show value in inches
THEN
P/1000 -> W
ROUND(W,4) -> W
OUTPUT(3,13,"TO")
OUTPUT(4,1,W)
GO TO C
END
OUTPUT(4,2,O)
OUTPUT(4,7,"REV PLUS")
ROUND(P,1) → W    reusing W for rounded dial (xxx.x)
OUTPUT(5,2, W)
OUTPUT(5,7,"THOU")
LBL C
OUTPUT(7,1,"PRESS ENTER, -")
OUTPUT(8,1,"OR 5 TO PAUSE.")

WHILE 1
GetKEY → W
While W=0
GetKEY → W
END
ClrHome
DISP W
PAUSE

```

IF W=105 "ENTER" detected so clear reverse flag and return
THEN
0 → W W=0 means continue on to next cut
RETURN
END

IF W=85 "-" detected so set reverse step flag and return
THEN
1 → W W=1 means back up on step
RETURN
END

IF W=83 "5" detected so PAUSE. In this state, the calculator
will automatically power down in a few minutes
and when powered up again, return to this point in
the program.

THEN
ClrHome
OUTPUT(1,1," PAUSE MODE:")
OUTPUT(3,2,"LEAVE POWER ON")
OUTPUT(4,1," AND LET CALC")
OUTPUT(5,1," POWER DOWN.")
OUTPUT(7,1,"PRESS -ENTER- TO")
OUTPUT(8,1,"RETURN TO PASS.")
PAUSE
GO TO A
END

END

PrgmBTU71	take into consideration radius/diameter dial. W=1 flags request to back up to previous location go to next step or go back one if possible
IF W>0	flag = 1 means return to the top of the loop with decremented or unchanged count value
THEN	
GO TO A	give last location again
END	
K+1 → K	for normal loop cycle, increment K
GO TO B	end of loop rough cutting from equator to right end
RETURN	
END	

BTU71 back up on step if possible

```
ClrHome  
DISP W  
DISP K  
PAUSE
```

```
IF W>0 AND K> OR = 1            if back up flag set and loop count,  
                                  K>0, decrement K
```

```
THEN  
K-1→K                    decrement K so user will be at previous step  
1 → W                    flag that we must return to top of FOR loop  
RETURN  
END
```

```
IF W>0 AND K<1            if back up flag set but K=0, can't back up any more
```

```
THEN  
ClrHome  
OUTPUT(3,1,"ERROR, AT START "  
PrgmBTU0                    prompt and pause  
1 → W                    flag that we must return to top of FOR loop without  
                                  decrementing K
```

```
RETURN  
END
```

```
-1 → W                    else, flag to continue in FOR loop  
RETURN                    and go to first line of FOR loop  
END
```

BTU8 make equator to origin finish cuts

A/2 → [A](1,3) initialize form vector for finish cut
F/2 → [A](1,4)
F/2 → [A](1,5)
PrgmBTU11 tell user to back cutter away from max OD

IF R=1 if this is a crown cut, distance is H-D
THEN
H- (0.001*D) → S inches
ELSE
A/2 → S inches; if this is a ball cut, distance is finish radius of ball
END

iPart(S/(.0001*E)) → I calc # of Z steps to go from equator to right end

0→K start of loop similar to FOR(K,0,I) except I can modify K
LBL B

IF K>I
THEN
RETURN
END

LBL A
0.001*K*E → W in inches
S- W + (.001*D) → Z in inches
PrgmBTU12 take Z and generate X in thou
PrgmBTU61 output next (X,Z) pair saying to move Z first and then X;
take into consideration radius/diameter dial
end of loop rough cutting from equator to right end
PrgmBTU71 go to next step or go back one if possible

IF W>0 flag = 1 means return to the top of the loop with
decremented or unchanged count value

THEN
GO TO A give last location again
END

K+1 → K for normal loop cycle, increment K

GO TO B
END

PrgmBTU12	take Z and generate X in thou
PrgmBTU61	output next (X,Z) pair saying to move Z first and then X; take into consideration radius/diameter dial
PrgmBTU71	end of loop finish cutting from equator to right end go to next step or go back one if possible
IF W>0	flag = 1 means return to the top of the loop with decremented or unchanged count value
THEN	
GO TO A	give last location again
END	
K+1 → K	for normal loop cycle, increment K
GO TO B	
RETURN	
END	

BTU10 using a left hand cutter, cut finish pass on shank

```
IF B = 0          if the shank finish diameter is zero, skip finish pass
THEN
RETURN
END
```

```
ClrHome
OUTPUT(1,1,"CHANGE TO")
OUTPUT(2,1,"LEFT HAND"
OUTPUT(3,1,"CUTTER")
PrgmBTU0        pause and wait for ENTER
OUTPUT(1,1,"SET X = 0 AT")
OUTPUT(2,1,"RIGHT END")
OUTPUT(3,1,"OF SHANK")
OUTPUT(4,1,"AND CUT FINAL")
OUTPUT(5,1,"OD OF SHANK.")
PrgmBTU0        pause and wait for ENTER
RETURN
END
```

*BTU11 tell user to back parting tool away from
max OD*

```
ClrHome  
OUTPUT(1,1,"BACK PARTING")  
OUTPUT(2,1,"TOOL AWAY")  
OUTPUT(3,1,"FROM MAX OD")  
PrgmBTU0  
RETURN  
END
```

BTU12 - translate any Z in inches less than the diameter of the ball and return X in thou; uses vector [A] to set size and location from origin

Calling program has already offset Z to compensate for parting tool width when at values of Z greater than the equator. Here I remove that compensation in order to get X.

```
IF Z < or = [A](1,4)                if Z is to right of equator
THEN
Z → [A](1,8)                          then use it directly
ELSE                                    if Z is to left of equator

Z - 0.001*C → [A](1,8)                then subtract width of parting tool
END
```

$1000 * ([A](1,5) - \text{SQRT}([A](1,3)^2 - ([A](1,4) - [A](1,8))^2)) \rightarrow X$ this single line defines a ball for both roughing and finish passes

```
RETURN
END
```

Test Cases

Ball - radius dial

Parting tool 100 thou

Finish DOC 10 thou

Finish step size 50 thou

Crossfeed: have dial, sets radius, dial size 100 thou

Profile: ball

Finish diameter .5

Finish shank diameter .2

Turn .52 diameter for .496 inches

Turn shank .22" diameter

Z, inches	X (revolutions/thou)	
.26	0/0	equator to right end roughing
.173	0/14.9	
.087	0/66.2	
0	2/60	
.36	0/0	equator to shank end roughing
.439	0/12.1	
.517	0/52.8	
.596	1/50	
.26	0/10	equator to right end finishing
.21	0/15.1	
.16	0/30.9	
.11	0/60	
.06	1/10	
.01	2/60	
.36	0/10	equator to shank end finishing
.41	0/15.1	
.46	0/30.9	
.51	0/60	
.56	1/10	

Ball - diameter dial

Parting tool 100 thou

Finish DOC 10 thou

Finish step size 50 thou

Crossfeed: have dial, sets diameter, dial size 200 thou

Profile: ball

Finish diameter .5

Finish shank diameter .2

Turn .52 diameter for .496 inches

Turn shank .22" diameter

Z, inches	X (revolutions/thou)	
.26	0/0	equator to right end roughing
.173	0/29.7	
.087	0/132.4	
0	2/120	

Abort the rest.

Ball - diameter DRO

Parting tool 100 thou

Finish DOC 10 thou

Finish step size 50 thou

Crossfeed: have DRO, sets diameter

Profile: ball

Finish diameter .5

Finish shank diameter .2

Turn .52 diameter for .496 inches

Turn shank .22" diameter

Z, inches	X (inches)	
.26	0	equator to right end roughing
.173	.0297	
.087	.1324	
0	.52	

Abort the rest.

Crown

Parting tool 100 thou

Finish DOC 10 thou

Finish step size 10 thou

Crossfeed: have dial, sets radius, dial size 100 thou

Profile: crown

Finish diameter 5

Finish shank diameter 1

Turn 1.02 diameter for length of shank

Z, inches	X (revolutions/thou)	
.052	0/0	roughing pass to right end but no cut occurred
0	5/10	finish pass to right
0.052	0/51.7	
.042	1/9.1	
.032	1/76.4	
.022	2/61.7	
.012	4/1.4	

Cut final OD of shank

Full radius

Parting tool 100 thou

Finish DOC 10 thou

Finish step size 50 thou

Crossfeed: have dial, sets radius, dial size 100 thou

Profile: full radius

Radius in inches 0.125

Finish shank 1

TURN DIAMETER OF DISK PLUS 20 THOU FOR OAL OF .27 INCHES

Turn shank to 1.02" for length

BTU6

Z, inches X(revolutions/thou)

.135	0/0
.068	0/18.1
0	1/35
.235	0/0
.303	18.1
.37	1/35
.135	0/10
.085	0/20.4
.035	0/60
.235	0/10
.285	0/20.4
.335	0/60

TURN SHANK TO FINISH DIA.