## Centering Parts In A Drillpress, Version 1.0

## By R. G. Sparber

Protected by Creative Commons.<sup>1</sup>

Back on February 4<sup>th</sup>, 2019, I published a video showing how to center stock on a drill press

https://www.youtube.com/watch?v=L8aN0wZ5O\_k&t=34s

I was using scrap pieces of round stock which worked fine until I ran out of capacity in my drill chuck. This solves my problem:



Each tool is made from aluminum round stock with the end turned down to about 3/8-inch.



With a piece of 5/8 strap in my drill press vise, I installed the 5/8 tool in my chuck. Just lowered the chuck down until the tool entered the gap. Locked the vise in place and I was centered.

You can also see that I used a fence. This let me first set center, lock the fence, and then move the vise to where I wanted the drill.

R. G. Sparber June 4, 2019 Page 1 of 2

<sup>&</sup>lt;sup>1</sup> This work is licensed under the Creative Commons Attribution 4.0 International License. To view a copy of this license, visit http://creativecommons.org/licenses/by/4.0/ or send a letter to Creative Commons, PO Box 1866, Mountain View, CA 94042, USA.

I welcome your comments and questions.

If you wish to be contacted each time I publish an article, email me with just "Subscribe" in the subject line. If you are on this list and have had enough, email me "Unsubscribe" in the subject line.

Rick Sparber <u>Rgsparber.ha@gmail.com</u> Rick.Sparber.org